



EXHIBIT S-65 000001

3/28/89 #E-7

Hoalua Stream Intake  
(retake of D-5)

000002



000003

MAY 89 1

Processing Services

Kodak

MAY 89 1

Processing Services

Kodak

5/4/89

# J-24 Lowrie Ditch - Hoalue Stream intake

000004

000005

5/10/89

# RI-23

New Hamakua - East  
Hamakua stream intake  
by # 1 overflow .  
000006

000007

5/10/89  
# 0-3 Wailoa Ditch-Hoalua  
2" pipe intake 000008

*Hodakuk*  
Processing Services  
MAY 89 I

*Hodakuk*  
Processing Services  
MAY 89 I



000009

MAY 89 1

Processing Services

**KODAK**



MAY 89 1

Processing Services

**KODAK**



5/10/89

# 0-4

New Hamakua - Hoalua stream  
intake

000010

A vertical photograph of a weathered wooden post standing in a dark, leaf-strewn area. The post is heavily stained and shows signs of decay. It is positioned in front of a dense thicket of green ivy and other foliage. The ground is covered with fallen leaves and debris. A bright orange glow is visible in the upper right corner.

000011

5/10/89

# 0-5 Wailoa Ditch- West Hoalua  
stream small intake  
000012

Kodak

Processing Services

MAY 89 I

Kodak

Processing Services

MAY 89 I



000013

5/10/89

# 0-6 New Hanakau - West Hanakau  
Stream small in lake 000014

~~Kodak~~ ~~Kodak~~

Processing Services

MAY 89 I

~~Kodak~~ ~~Kodak~~

Processing Services

MAY 89 I



000015

MAY 89 1

Processing Services

ModiaX



MAY 89 1

Processing Services

ModiaX



5/10/89

# 0-7 New Hamakua - West Hoalua stream  
small intake (Ephriems i 000016)