



EXHIBIT S-68 000001

5/4/89
J-19

Lowrie Ditch - Main
Nailiihaele Stream 000002

Kodak
Kodak

Processing Services
MAY 89 I

Kodak
Kodak

Processing Services
MAY 89 I



000003

Hodalux
Processing Services

MAY 89 1

Hodalux

Hodalux
Processing Services

MAY 89 1

Hodalux

5/4/89
#J-20

Spreckels Feeder Ditch - Main
Alailiihaele Stream intake

000004



000005

5-19-89

N-5 Wailoa Ditch - Alailii haele
stream - Papaea long intake 000006

A photograph of a dark, rectangular structure, possibly a concrete or stone block, partially buried in the ground. The structure is covered in moss and surrounded by fallen leaves, twigs, and some green plants growing from the top. The overall scene is dimly lit, suggesting it might be nighttime or in a shaded area.

000007

5/9/89
N-6

Waipa Ditch - Naiilihihale
stream - Papaea #3
intake 000008

000009

5/9/89

N-7 Wailoa Ditch - Alailii Stream - Brian's 2" pvc
intake to cross 000010



000011

5/9/89

N-8 New Hamakua - Nailiihihae
stream - #2 intake/overpass
000012

A dark, overexposed photograph showing a stream flowing through a dense forest. The water is dark and reflects the surrounding greenery. Large green leaves are visible on the left side. The overall image is very dark and lacks fine detail due to overexposure.

000013

5/9/89

N-9 Wailoa Ditch - Kaiilihihale
stream. Papadea #3 intake 000014



000015

5/9/89

N-10 New Hamakua - Nailiihiwae
stream - Papaea #³000016
intake by control gate



000017

5/9/89

11-11 New Hamakua - Hailihale Stream -
West Papaea 2" pvc pipe intake
000018



5/9/89

N-12 Wailoa Ditch - Naiilihi Hale stream
main intake

000020



00002

5/9/89

N-13 Wailea Ditch - Kaiilihiwae Stream
1" driscoe pipe intake into overflow
000022



000023

5/9/89

N1-4 New Hamakua - Nailiihaele Stream
Papaaca long intake/overpass
(# 1 intake) 000024



000025

5/189

NJ-14 Nea Hamakua - Nailiiilihae
stream main intake 000026



000027

5/9/89

N-16

Wailoa Ditch - West Kailiilihaele
stream siphon puka intake

000028