



STATE OF HAWAII
DEPARTMENT OF LAND AND NATURAL RESOURCES
COMMISSION ON WATER RESOURCE MANAGEMENT
 Stream Protection and Management Branch

FIELD INVESTIGATION REPORT
FI2009021006 (East Maui, Na Moku Project Taro)

Date of Field Investigation: February 11, 2009		Time (24-hour): 1600 - 1730	
CWRM Staff: Ed Sakoda, Dean Uyeno, and Chui Ling Cheng			
Individuals Present:			
Hydrologic Unit: Waiokamilo (6055)			
Stream Name: Waiokamilo Stream			
Findings:			
<p>The purpose of this field visit was to get a better understanding of the of the taro patches of the Na Moku Project, with main focus on the water flow from its sources and through the taro patches before water returns to the stream. CWRM staff collected the following information: 1) water flow through the patches; 2) auwai system and location in relation to the patches; 4) locations of return flow from the auwai to the stream; and 5) where flow enters the auwai from the stream.</p> <p>Taro patches in the Na Moku Project were fed by Waiokamilo Stream. Most of the patches were in cultivation.</p> <p>Staff left the Na Moku Proectt at 1730 hours, and continued to document flow conditions in some of the streams included in the other 19 petitioned East Maui streams. Refer to Field Investigation Report FI2009021107 (East Maui, Stream Condition) for more information.</p>			
Image Listing: (Attach PDF of image contact sheet)			
File Name:	Brief Description:		
20090210054	Taro patches of the Na Moku Project.		
20090210056	Taro patches of the Na Moku Project.		
20090210058	Taro patches of the Na Moku Project.		
GPS Listing:			
Shapefiles: (List file names of all shapefiles created and a brief description of each)			
File Name:	Brief Description:		
Waypoints: (List all waypoints in decimal degrees and provide a brief description of each)			
WP No.	Latitude	Longitude	Brief Description:
Attachments:			
Brief Description:			
1. Image Contact Sheet			
Recommendations:			

IMAGE CONTACT SHEET



20090211054.jpg



20090211056.jpg



20090211058.jpg